

CETAC TECHNOLOGIES

SERVICE BULLETIN

Subject: Z drive assembly replacement on ASX-500.	Bulletin No:	SB0904
	Date Issued:	10/18/96
	Priority:	Low

Product: ASX-500

Serial Numbers: Prior to 099617 ASX
Serial Numbers start by month (MM), year (YY) and units built that month (i.e., MMYyxx)

Service Location: Customer Site CETAC Technologies

Responsibility: Customer Trained CETAC Representative

Replacement Parts: Customer CETAC Technologies

DESCRIPTION

A design change was made to the Z drive assembly part number (SP5223). The changes that were made include lengthening the sipper probe and the sipper probe support. Modifications were also made to the guide block assembly. These modifications include changing the dimensions of the sipper guide plate orifice and tolerances of the guide block.

IMPLEMENTATION

Upon damage to any autosampler Z drive assembly or guide block assembly a new Z drive assembly will need to be ordered. The assembly will include the sample probe assembly, guide block and sample probe.

PARTS

Part Number	Description
SP5223	Z drive assembly

AVAILABLE DOCUMENTATION